

Updated URGENT MEDICAL DEVICE CORRECTION

Medfusion[™] Syringe Infusion Pumps – Syringe Recognition Barrel Clamp Guide Expansion (3010, 3010A and 3010E)

11 March 2024

Dear Valued Medfusion Customers:

- Director of Pharmacy
- Director of Nursing
- Director of Risk Management

On February 12, 2018, Smiths Medical advised you about a potential issue with certain Medfusion Model 3010, 3010A, and 3010E syringe infusion pumps manufactured or serviced with specific lots of Barrel Clamp Guides. Smiths Medical is issuing this updated communication to make you aware of three additional lots of affected Barrel Clamp Guides and the actions taken by Smiths Medical. Please review all products in your inventory to determine if they are affected by the issue in this notice. Table 1 below identifies the additional (3) lots.

Affected Products:

Medfusion Model 3010, 3010A, and 3010E pumps serviced with the lots of Barrel Clamp Guide (Part Number G6000716) listed below are potentially affected by this issue.

This includes:

- Medfusion Model 3010, 3010A, and 3010E pumps serviced with these potentially affected Barrel Clamp Guides between Jul-2016 and Feb-2019.
- Individually sold Barrel Clamp Guides from the identified lots, distributed between Jul-2016 and Oct-2018.

Table 1:

Affected Barrel Clamp Guide Lots (Additional 3 Lots)		
P0407365		
P0486670		
P0561740		

Overview of the Issue:

Smiths Medical identified that certain Barrel Clamp Guides from the above lots may contain a molding defect that could potentially lead to slippage of the spring within the barrel clamp assembly. If this occurs, it could result in the inability of the pump to recognize a syringe or the pump may misidentify the size of the syringe loaded.

Potential Risk:

The inability of the pump to recognize a loaded syringe can potentially lead to a delay in the initiation of an infusion due to clinicians being unable to complete programming. Interruption of therapy may potentially occur if syringe recognition is lost during an active infusion. Note, the pump will display a visual and audible alarm in this scenario. Misidentification of the syringe size may potentially result in over-delivery or under-delivery if the clinician does not verify the syringe size prior to starting an infusion.

As reported in the 2018 communication, Smiths Medical had received one (1) report of a serious injury potentially related to this issue. There are no new reports of serious injury or death.

<u>Customer Required Actions – Medfusion Infusion Pumps:</u>

- Locate any affected Medfusion Syringe Pumps that may be in your possession by referring to the
 list of affected devices included with the Response Form. This list includes any specific pump
 model/serial number(s) your organization purchased that were manufactured or serviced with
 potentially affected Barrel Clamp Guides. Each pump has a unique serial number found on the
 label on the bottom of the pump.
- 2. You may continue to use the pumps but utilize the Syringe Verification Reference Tool originally included with the 2018 Notice (also provided as Attachment 2 of this communication).

Customer Required Actions – Individually Sold Barrel Clamp Guides:

- Locate any affected Barrel Clamp Guide (Part Number G6000716) lots in your parts inventory or within the Medfusion Syringe Pump(s) you have repaired at your facility. NOTE – If you have purchased affected individually sold Barrel Clamp Guides, the Response Form included with this notice will indicate the order numbers shipped to your organization and a Return Label will be provided.
- 2. If any potentially affected Barrel Clamp Guides have already been installed in pumps, you may continue to use the pumps, but utilize the Syringe Verification Reference Tool originally included with the 2018 Notice (also provided as Attachment 2 of this communication).

<u>Customer Required Actions – All Customers</u>

- Ensure all users or potential users of these devices are immediately made aware of this notification and proposed mitigations.
- Complete and return the attached Response Form via fax at 1-800-517-3560 or email to <u>smithsmedical3853@sedgwick.com</u> within ten days of receipt to acknowledge your understanding of this notification.
- DISTRIBUTORS: If you have distributed potentially affected products to your customers, please immediately forward this notice to them. Ask them to contact Sedgwick at 1-866-535-5095 (M-F, 8am-5pm ET) to obtain a Response Form.



For further inquiries, please contact Smiths Medical using the following information:

Smiths Medical Contact	Contact Information	Areas of Support
Global Complaint Management	globalcomplaints@icumed.com 1-(866)-216-8806	To report adverse events or product complaints
Technical Support	icumed.custhelp.com/app/market- action	Additional information or technical assistance
Field Corrections	icumed.custhelp.com/app/market- action	Questions about this Field Correction Notice

Smiths Medical's Actions:

Smiths Medical implemented the corrective actions necessary to address the manufacturing variations that led to these issues.

General Information:

This notification is being performed with the knowledge of regulatory authorities, including the US Food and Drug Administration (FDA). If you wish to contact the FDA regarding any adverse events or quality problems associated with this notice, use the following contact information.

- www.fda.gov/medwatch
- 1-888-463-6332

Smiths Medical is committed to providing quality products and service to our customers. We apologize for any inconvenience this situation may cause.

Sincerely,

Jim Vegel

)im Vegel

Vice President of Quality

Enclosures:

Attachment 1 – Response Form

Attachment 2 – Syringe Verification Reference Tool

Additional Verification of Medication Syringe Model and Size After Start of Infusion*

When programming an infusion, you will be prompted to confirm the model and size of the syringe that has been loaded into the pump. Before starting any delivery, always confirm the accuracy of all infusion values to the original order. When you begin the infusion, you can confirm the model and size of the syringe again by following the instructions below.


If the syringe is not recognized or is read as an incorrect size during any part of the programming or the infusion, remove the pump from service for repair by a trained biomedical technician.



1) After programming and priming your infusion, you will see instructions at the top of the screen prompting you to begin the infusion.



2) Press the start button to begin the infusion.



3) Very briefly, the syringe model and size will show in the upper left hand corner, before defaulting to showing the drug protocol you are delivering. Use this to re-verify the size of the syringe you are using.



4) If you miss the size on the screen, pressing the back button on the pump will again briefly flash the size of the syringe in the upper left hand corner without stopping the infusion. The screen will then return to the normal run screen.

^{*}Please refer to the Operator's Manual for complete instructions, indications, contraindications, warnings and precautions.

3853_08_03AS_V1.1